

MI/RR IPM

	2020-10						2020-11				2020-12					2021-1				2021-2				2021-3				
		41	42	43	44	45	46	47	48	49	50	51	52	53	1	2	3	4	5	6	7	8	9	10	11	12		
AD Instrumentation	AD Instrumentation																											
MI/RR IPM																												
Single turn plot does not work when (...)	New																											
Necessary LabView parameters are no (...)	Resolved																											
State machine devices for Booster IPMs	Resolved																											
Plotting Charge, Sigma and Turns does (...)	New																											
Single turn plot not showing current (...)	Resolved																											
Excessive delay in first plot, capturing (...)	New																											